

---

## **Readme for DIGSI 5 V3.00 Hotfix 1**

### **New Features and Modifications**

DIGSI 5 V3.00 Hotfix 1 addresses the following issue:

Communication between DIGSI 5 and SIPROTEC 5 devices is blocked since 30<sup>th</sup> of September 2013.

### **Notes on Usage / Restrictions**

DIGSI 5 V3.00 must be installed on your computer.

### **Compatibility**

DIGSI 5 V3.00 Hotfix 1 is only tested to update DIGSI 5 V3.00.

If you are running a previous version of DIGSI 5 you have to update to DIGSI 5 V3.00

### **Contents of the Consignment**

DIGSI 5 V3.00 Hotfix 1 contains following files:

- SSL.NET.dll
- DIGSI5-V3.00\_HF1\_Readme.pdf

### **Installation**

1. Make sure that DIGSI 5 V3.00 is installed on your PC.
2. Please close DIGSI 5 V3.00 before you install the Hotfix 1.
3. Copy the file SSL.NET.dll into the folder "...DIGSI 5 V3\Bin". This is depending on your DIGSI 5 installation. The default installation path is "C:\Program Files (x86)\Siemens Energy\DIGSI 5 V3". Depending on your operating system this can require administrator rights!
4. Confirm the question whether to overwrite the existing file with "Yes".

### **Remarks to Installation**

How to recognize that DIGSI 5 V3.00 Hotfix 1 has been installed:

Right click the copied SSL.NET.dll and open the "Properties". Select the "Details" tab and check if the "Product version" shows 3, 2, 0, 0.

### **Uninstallation**

It is neither possible nor necessary to uninstall the DIGSI 5 V3.00 Hotfix 1.

---

## **Support**

For questions about DIGSI 5, please contact the Siemens Customer Support Center.

Fon: +49 (180) 5 24-8437

Fax: +49 (180) 5 24-2471

E-mail: [support.ic@siemens.com](mailto:support.ic@siemens.com)

FAQ: <http://www.siemens.com/energy-support>