

- de** Montageanleitung
- en** Mounting instructions
- fr** Instructions de montage
- sv** Monteringsinstruktion
- nl** Montage-aanwijzing
- it** Istruzioni di montaggio
- fi** Asennusohje
- es** Instrucciones de montaje
- da** Monteringsvejledning


- Tauchtemperaturfühler**
- Immersion temperature sensor**
- Sonde de température à plonger**
- Dykgivare**
- Dompeltemperaturopnemer**
- Termosonda di mandata a immersione**
- Vesianturi**
- Sonda de temperatura de inmersión**
- Dykrørsføler**

QAE3010...





QAE3075...



QAE3010...




QAE3075...



- de** Maßbilder
- en** Dimensions
- fr** Encombremnts

- sv** Måttuppgifter
- nl** Maatschets
- it** Ingombri

- fi** Mittapiirros
- es** Dimensiones
- da** Målskitse



Typ	A [mm]
QAE3010.010	100
QAE3010.016	160
QAE3075.010	100
QAE3075.016	160

Maße in mm
 Dimensions in mm
 Dimensions en mm
 Mått i mm
 Maten in mm
 Dimensioni in mm
 Mitat mm
 Dimensiones en mm
 Mål i mm