
Description: TOOLBOX II Version 5
Item number: S38-100
Revision: V05.00_HF15

Date of Release: 2013-04-11

V5.00 HOTFIX 15 (english)

-- Installation --

Cumulative hotfix installation

Hotfix 15 replaces all released hotfix installations of TOOLBOX II Version 5.0.

After new setup of TOOLBOX II Version 5.00 only hotfix 15 has to be installed.

Operating systems with enabled UAC (User Account Control)

This hotfix must be installed with administrator permissions on the following operating systems:

- Microsoft Windows 7
- Microsoft Windows Vista
- Microsoft Windows Server 2008 R2

Start setup with popup menu "Run as administrator" in Windows explorer

Client/Server mode

This hotfix must be installed on client and server.

Hotfix 15 includes the following changes:

-- FAULT CORRECTIONS --

* SICAM MIC/Support for CPC60 from Rev. 24 (CHDOC00067838)