

de Montageanleitung
en Mounting instructions
fr Instructions de montage
sv Monteringsinstruktion
nl Montage-handleiding
it Istruzioni di montaggio
fi Asennusohje
es Instrucciones de montaje
da Monteringsvejledning

Stellantriebe für Hahnen
Actuators for slipper valves
Servomoteurs vannes à secteur
Ställdon för vridslidventiler
Servomotoren voor kranen
Servomandi per valvole a settore
Venttiilien toimimootorit
Forstillingsorganer sleidehaner
Motorer for haner

SQK349.00

VB.../VC...
 DN20...50 (S 02)

4508Z01

4511Z02

AC 230 V ± 15 %
 50 Hz / 60 Hz
 IP42 IEC 529/ DIN 40 050
 II IEC 730 / VDE 0631
 -15° ... +50 °C

1

4508Z02

2

SQK349.00

VBI31...
 VBG31...
 VBF21...
 DN40+50
 VCI31...
 Serie 02

00113

